

RECORDED INTELLIGENCE

TIME	ORIGIN	AS KNOWN ON 89-01-16
00:00	Fire Bell (cancelled immediately)	
00:03½	Intercom chime	
00:04	Joe	What's going on here?
00:06	?	Uh
00:08	Alan	Cargo
	Alan	It's just come on now afterwards
	Capt ?	Where exactly?
	Alan	Its the main deck
	?	What was that?
	Alan	Main deck cargo
	Alan	Then the other one came on as well, weve, got two.
	Alan	Should I push the button as well?
	Joe	Ja
	Capt	Lees vir ons die checklist daar - hoor
	?	Dit lyk aan (?)
	Alan	Checklist main deck cargo light on
	Joe	Ja
+21	Capt	Die feit dat al twee aangekom het, verChime (?) my
	Alan	Oh shit

Test tone :

800 HZ test tone introduced on all four channels. After 6 seconds the tone starts to warble due to degradation of the tape. 7 seconds later the tape ends.

01:22

Failure mode

NOTE:

The 800 HZ test signal has been introduced on all 4 channels probably by a fire induced short circuit in the wire bundle. The short unrecorded portion of the tape that is always present at the erase head is not there. A possible cause is low voltage, resulting from the degradation of the wire bundle insulation, which will effect the erase bias oxillator before the record or drive circuits.